

OMMS

Status

Completed

Note

Upon investigating the source of the leak, HCPSS Building Services discovered that approximately 1 linear foot of insulation (above the ceiling) had mold growth. The source of the leak has been repaired. The impacted insulation is being removed and fully addressed today. The location of the HVAC leak was in the hallway between the media center and 7th grade classrooms. We are grateful to our custodians for promptly identifying evidence of the leak and to HCPSS building services for their prompt support to resolve this concern. There was and will not be any disruption to the school day or instructional activity in addressing the concern. All relevant information will be posted on our IEQ page shortly. As always, you are welcome to contact me with any questions or concerns.

Date Submitted

Thursday, May 17, 2018

Location

the hallway between the media center and 7th grade classrooms

Date Completed

Friday, May 18, 2018